

http://www.samaterials.com

# Stanford Advanced Materials

We not only sell products, we provide satisfactions.
72 Fairbanks Suite 100, Irvine, CA 92618, USA

Tel: (949) 407-8904 Fax: (949) 812-6690

Current Version: 2.0 Revision Date: Sep 5, 2012

# **Material Safety Data Sheet**

Identity: Cadmium Selenide Formula: CdSe

#### **SECTION I - GENERAL INFORMATION**

Manufacturer: Stanford Advanced Materials (SAM)

The information below is believed to be accurate and represents the best information available to SAM. However, SAM makes no warranty, expressed or implied with respect to such information and assumes no liability resulting from its use.

#### SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

CAS # OSHA PEL ACGIH TLV %

1306-24-7

## SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

Physical States: Powder

Boiling Point: N/A Vapor Pressure (vs. air or mmHg): N/A

Melting Point: >1350 C (>2462 F) Density:  $5.81 \text{ g/cm}^3$  Evaporation Rate: N/A Flash Point: N/A

Solubility in water: Insoluble

Appearance and odor: Red, black, odorless

## SECTION IV - FIRE AND EXPLOSION HAZARD DATA:

Method Used: Explosive Limits: LEL: N/A UEL: N/A Extinguishing Media: Use suitable extinguishing agent for surrounding material and type of fire

Special Fire Fighting Procedures:

Firefighters must wear full face, self-contained breathing apparatus with full protective clothing to prevent contact with skin and eyes. Fumes from fire are hazardous. Isolate runoff to prevent environmental pollution.

Suitable extinguishing agents:

Product is not flammable. Use fire fighting measures that suit the surrounding fire.

Special hazards caused by the material, its products of combustion or resulting gases:

In case of fire, the following can be released: Toxic metal oxide fume.

#### SECTION V - REACTIVITY DATA



http://www.samaterials.com

# Stanford Advanced Materials

We not only sell products, we provide satisfactions.

72 Fairbanks Suite 100, Irvine, CA 92618, USA Tel: (949) 407-8904 Fax: (949) 812-6690

Thermal decomposition / conditions to be avoided:

Decomposition will not occur if used and stored according to specifications.

Materials to be avoided:

Acids.

Dangerous reactions:

No dangerous reactions known.

Dangerous products of decomposition:

Hydrogen selenide, Toxic metal oxide fume.

## SECTION VI - HEALTH HAZARD DATA

Routes of entry: Inhalation? Yes Skin? Yes Eyes? Yes Ingestion? Yes

Acute Toxicity: Primary Irritant Effect:

On the Skin: Irritant to skin and mucous membranes.

Target Organs: Irritating effect.

Sensitization: No sensitizing effects known.

Subacute to chronic toxicity: Cadmium and cadmium compounds and highly toxic and experimental carcinogens. Exposure affects the respiratory tract, kidneys, and liver.

Ingestion may cause nausea, salivation, vomiting and diarrhea. Ingestion or inhalation of cadmium/cadmium compounds may be fatal. Selenium may cause amyotrophic lateral sclerosis, bronchial irritation, gastrointestinal distress, vasopharyngeal irritation, garlic odor on breath and sweat, metallic taste, pallor, irritability, excessive fatigue, loss of finernails and hair, pulmonary edema, anemia and weight loss.

## Emergency and First Aid Procedures:

Inhalation: Remove victim to fresh air, keep warm and quiet, and give oxygen if breathing is

difficult; seek medical attention

Ingestion: Give 1-2 glasses of milk or water and induce vomiting, seek medical attention. Never

induce vomiting or give anything by mouth to an unconscious person

Skin: Remove contaminated clothing, brush material off skin, wash affected area with mild soap and

water, and seek medical attention if symptoms persist

Eye: Flush eyes with lukewarm water, lifting upper and lower eyelids for at least 15 minutes and seek

medical attention

## SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be taken in case material is released or spilled:

Wear appropriate respiratory and protective equipment specified in section VIII. Isolate spill area, provide ventilation and extinguish sources of ignition. Vacuum up spill using a high efficiency particulate absolute (HEPA) air filter and place in a closed container for proper disposal. Take care not to raise dust.

Waste disposal method:

Dispose of in accordance with state, local, and federal regulations.

#### Hazard Label Information:

Store in cool, dry area and in tightly sealed container. Wash thoroughly after handling.



Stanford Advanced Materials

We not only sell products, we provide satisfactions.
72 Fairbanks Suite 100, Irvine, CA 92618, USA

Tel: (949) 407-8904 Fax: (949) 812-6690

http://www.samaterials.com

## SECTION VIII - CONTROL MEASURES

Protective Equipment Summary (Hazard Label Information):

NIOSH approved respirator, impervious gloves, safety glasses, clothes to prevent contact.

## Ventilation:

Local Exhaust: To maintain concentration at low exposure levels.

Mechanical (General): Recommended.

## Work/Hygienic/Maintenance Practices:

Implement engineering and work practice controls to reduce and maintain concentration of exposure at low levels. Use good housekeeping and sanitation practices. Do not use tobacco or food in work area. Wash thoroughly before eating or smoking. Do not blow dust off clothing or skin with compressed air.

Please be advised that N/A can either mean Not Applicable or No Data Has Been Established